


W2S



PL: INSTRUKCJA MONTAŻU

EN: ASSEMBLY MANUAL

CZ: PŘÍRUČKA PRO MONTÁŽ

SK: PRÍRUČKA PRE MONTÁŽ





DE: MONTAGEANLEITUNG

SR: UPUTSTVO ZA INSTALACIJU


NL: MONTAGE-INSTRUCTIES

PROWANSJA

W2S GN/GY




A1 x22




Ø8x35mm

B1 x24




Ø5x38mm

C1 x24




Ø15x12mm

E1 x12




Ø5x16mm

E10 x1




43x43mm

F2 x4




40mm

G2 x20




14x14mm

J11 x16



Ø21mm

K1 x12




Ø6,4x50mm

N2 x1




4mm HEX

P2 x4




350mm

R1 x3




24x24x19mm

T1 x2




76x15mm

U13 x2




Ø33mm

U14 x2




92x33mm

W2 x91




Ø3,5x16mm

W5 x4




Ø4x30mm

X4 x2



M4x25mm

X2 x4




M4x16mm

Y1 x8




Ø8x1,5mm

Y2 x7







Ø16mm

Z6 x6












Ø35mm, 90°







nr	L[mm]	W[mm]	H[mm]	PCS	BOX
1	120	350	15	2	1/3
2	120	350	15	2	1/3
3	120	333	15	2	1/3
4	1873	876	2,5	1	2/3
5	360	355	2,5	2	1/3
6	1940	400	15	1	2/3
7	1940	400	15	1	2/3
8	1940	50	22	1	2/3
9	1940	50	22	1	2/3
10	395	1678	18	2	3/3
11	189	395	18	1	3/3
12	189	395	18	1	3/3
13	868	382	15	1	1/3
14	901	430	22	1	1/3
15	174	382	15	1	1/3
16	868	400	15	1	1/3
17	868	360	15	3	1/3
18	867	60	15	1	1/3

x2

1




x2



x2

2

B1 x4







Ø5x38mm

Y1 x4






Ø8x1,5mm



x2


3



x2

4

K1 x8




Ø6,4x50mm

N2 x1






4mm HEX








x2

5





x2

6







x2



7










8



9




10




11

P2 x 2




350mm

W5 x 4




Ø4x30mm




12

P2 x 2






350mm

W2 x 6




Ø3,5x16mm




13

A1 x 8





Ø8x35mm




C1 x 8





Ø15x12mm




14





15



16




17




18

G2x20







14x14mm

W2x20




Ø3,5x16mm




19

W2x6




Ø3,5x16mm




20

R1 x3




24x24x19mm

W2 x6



Ø3,5x16mm





21



Y2 x7





Ø16mm



22




23





24

I




II



25

E1 x12




Ø5x16mm

U13 x2




Ø33mm

U14 x2




92x33mm

X2 x4







M4x16mm



X4 x2




M4x25mm






26





27



W2x4




28




29

T1 x 2



76x15mm

W2 x 4



Ø3,5x16mm

100 mm

